

Divar firmware version history

Version 2.15

When upgrading from a previous Divar 2.x version all video and settings will be retained. Please use our new download tool (“divarload.exe” or the “Divar Firmware Download” from the 2.15 PC package) supplied with the downloaded firmware.

Warning: If you upgrade from Divar 1.x to Divar 2.x, the stored VIDEO WILL BE ERASED! Be sure to archive important pieces of video before upgrading! The settings will be retained.

This release includes the following new features:

- Six additional languages
The Divar, the PC software (Control Center, Configuration Tool, Archive Player) and the webserver pages now support the following additional languages: Danish, Swedish, Norwegian, Finnish, Czech and Hungarian.
- Bilinx camera input alarms
Divar Bilinx models now support handling of the alarm inputs from Bilinx enabled cameras. (Support is limited to the first input on the input alarm connector of a Bilinx enabled Dinion or AutoDome)
- Network time synchronization
It is now possible to synchronize a Divar with a NTP time server. All Divar models now support both the time synchronization via the ICMP (RFC792) and from version 2.15 onwards also the SNTP time synchronization protocols.
- Improved disk error handling
A new disk error handling algorithm has been added, improving overall hard disk drive reliability and lifespan.

This release also includes numerous small bug fixes.

Bosch strongly recommends upgrading to the latest firmware to achieve the best possible functionality, compatibility and performance.

Version 2.14

This version was never released.

Version 2.13

This release includes the following bug fix:

- Correct “Motion trigger” to start recording on the programmed IPS range when motion is detected.

Version 2.12

This release includes the following bug fix:

- If you update a Divar E or F model (non Bilinx models) to the firmware 2.11 and you power on the unit than a connected keyboard didn’t work anymore (the keyboard will start working after you disconnect and connect it again). This is corrected in firmware 2.12.

Version 2.11

This release includes the following new features:

- Using Internet Explorer, access the Divar to view live action or playback archived events
- Auto-protect video when an input alarm is triggered
- Support for Bosch G-series control panels
- Assign names to input alarms
- Change camera pre-position on a profile change
- Configure the bandwidth limit throttle to values between 0 and 1 Mbps

This release also includes some bug fixes resulting in:

- Correct DST time change behavior in a multiple-Divar setup
- Improved local archiving behavior

Version 2.10

This version was never released.

Version 2.03

This release includes some bug fixes related to ATM/POS.

Version 2.02

This release includes the following enhancements:

- General performance improvement
- Some additional ATM/POS display settings were added

This release includes the following bug fixes:

- Several ATM/POS issues were resolved
- Improved playback behaviour during stepping
- DVD+R's can be finalised correctly
- Local archiving of large clips has been improved

Version 2.01

This released was used for the Divar with internal DVD writer only and included support for the internal DVD writer.

Version 2.00

Warning: If you upgrade from Divar 1.x to Divar 2.0x, the stored VIDEO WILL BE ERASED! Be sure to archive important pieces of video before upgrading! The settings will be retained.

If you are upgrading your Divar from firmware version 1.x to 2.0x, the following new features will become available with this release:

- Daylight savings time support
- Auto-detect Divars for login on a local area network with the Control Center 2.0 PC software
- Login to multiple Divars at a time with the Control Center 2.0 PC software

To enable the following new features that are also present in version 2.00, a Divar 1.x software upgrade license is required:

- Smart motion search to search for motion in a user-defined area in recorded video
- Support for local archiving without the need for a PC (optional external DVD writer required)
- Search on ATM/POS data (optional ATM/POS license and ATM/POS bridge required)

Version 1.20

This release includes the following new feature:

- ADIM support

This release includes the following enhancement:

- Improved built-in service logging and system diagnostics for repair center usage

This release includes the following bug fixes:

- Recording more pre-event images than during normal and event recording, could result in system instability
- Improved disk handling: Self-reallocation of the storage medium could result in a drive being failed inadvertently

Version 1.12

This release includes a bug fix for:

- User Interface issue where a user could set the event (motion and input alarm) recording rates to an illogical number of images per second (below 1 IPS)

Version 1.11

This release includes the following enhancement:

- Configurable network port for video streaming

This release also includes the following bug fixes:

- Heavy keyboard usage might cause the Divar keyboard port to lock up
- Risk of data loss, on a DVAD storage array, after power failure eliminated

Version 1.10

This release includes the following new features:

- Remote configuration tool support; to allow for remote administration of the Divar
- Multiple disk array support; to allow for multiple disk arrays (DVAS or DVAD) to support long term storage
- Multi-user license (optional): to allow for multiple remote user access to a Divar at the same time

This release also includes the following enhancements:

- Enhanced handling of day/night cameras that switch off color burst
- Increased sample frequency for motion detection
- Enhanced disk status overview
- Improved network transmission speed

Version 1.03

This release includes the following enhancements:

- Enhanced Quick Install allowing motion recording and network setup
- Automatic activation of the Quick Install upon initial system power up
- Time synchronization between multiple Divars
- Increased sensitivity for motion detection
- Auto IP address assignment
- Record rate selection for 0 IPS, allowing event recording only
- Enhanced video quality of images with Constant Bit Rate for controlled file size
- Enhanced text color and background options

This release also includes some bug fixes resulting in:

- Improved system power up behavior
- Enhanced hard drive detection
- Enhanced video clip protection

Version 1.01

Initial version.